



**DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE
CHIEF WATER ANALYST'S LABORATORY, COIMBATORE - 18.**

From
Thiru.G.Subramanian,M.Sc.,M.Ed.,B.L.,
Chief Water Analyst,
219, Race Course Road,
Coimbatore - 641 018,
Ph.No: 0422-2221542,
E.mail: cwadph.cbe@gmail.com

To
GVK Vidhya Mandir,
2136, Trichy Road,
Singanallur,
Coimbatore - 641 005.

L.Dis.No.626/A3/2026, CWA/CBE, M.90,

Dated: 30.04.2026.

Sir,

Sub: Report on Examination of water sample from GVK Vidhya Mandir, 2136, Trichy Road, Singanallur, Coimbatore Collected on 21.04.2026.

A sample of water (Source: Pillur Dam Water - Corporation Supply) stated to have been collected on 21.04.2026 from the Water Doctor Purifier Outlet tap at Main building, Ground floor at GVK Vidhya Mandir, 2136, Trichy Road, Singanallur, Coimbatore by Thiru.S.K.Senthil Prabu, Administrative Supervisor was received at this laboratory on the same day from the above addressee to assess its suitability for drinking purpose.

The results of analysis are furnished overleaf.

The sample of water is Colourless and clear in physical appearance.

Judged by the results of analysis, it is of satisfactory Chemical and bacteriological quality for drinking purpose.

However the Water Doctor Purifier should be maintained periodically as per the Supplier's manual to get hygienic safe water at all times.

The Sump / OHT should also be cleaned atleast once in a month to maintain the hygienic condition.

M. B. 30/4/26

**CHIEF WATER ANALYST,
COIMBATORE - 18.**

2/20/4

M. B. 30/04/26

Copy to Lab / File

DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE			
CHIEF WATER ANALYST'S LABORATORY, COIMBATORE-641018			
RESULTS OF EXAMINATION OF SAMPLES OF WATER			
Samples from	GVK Vidhya Mandir, 2136, Trichy Road, Singanallur, Coimbatore – 641 005.		
Collected by	Thiru.S.K.Senthil Prabu, Administrative Supervisor		
Date of collection:	21.04.2026		
Date of Receipt :	21.04.2026		
	M.90		
Source as per Label	Water Doctor Purifier Outlet tap at Main building, Ground floor at GVK Vidhya Mandir, 2136, Trichy Road, Singanallur, Coimbatore		
Source	Pillur Dam Water - Corporation Supply		
Bacteriological Examination			
Plate count per ml.on agar at 37 ^o .C-24 hrs	40		
MPN of Coliform bacteria/100ml	0		
Nature of Coliform bacteria isolated	Negative		
Results of Vibrio test			
Physical Examination			
Colour	Colourless		
Turbidity	1		
Smell	None		
Chemical Examination(in mg/l)			
Total solids	130		
Carbonate Hardness (as CaCO ₃)	52		
Non-carbonate Hardness(as CaCO ₃)	8		
Total Hardness (as CaCO ₃)	60		
Chloride (as Cl)	19		
Ammonia cal Nitrogen (as N)	0		
Albuminoid Nitrogen (as N)	-		
Oxygen absorbed(Tidys test) in 4 hrs	0.12		
Nitrate nitrogen as N	0.5		
Acidity/Alkalinity} Phenolphthalein	0		
as CaCO ₃ } Methyl Orange	52		
Fluoride (as F)	0.1		
pH value	7.5		
Total Iron (as Fe)	0.05		
Manganese (as Mn)	-		
Qualitative Tests			
Nitrite Nitrogen	Trace		
Sulphate	Trace		
Phosphate	Trace		
Toxic Substance	-		
Electrical conductivity(Reciprocal megohms per cm at 20 ^o C)	180		
Microscopical Examination	Amorphous Matter		

CHIEF WATER ANALYST,
COIMBATORE-18.

21/30/4

20.8395
30/04/26